



Intervention Report

| | | | |
|--|--|-----------------------------------|----|
| Date of Report: 28/12/2017 | | Date of Intervention : 28/12/2017 | |
| Engineer's name: François-Joseph | | | |
| Station | | | |
| Name: Ramat Aviv | | MUX (CH) : MUX1 C26 | |
| Type of Transmitter: Gap Filler | | Output Power: 110W | |
| Failure information | | | |
| Description: | Output power drop. | | |
| Solution: | The fans of the Gapfiller wasnt working fine. I replaced them, everything was working good after that. | | |
| Material Exchange? | <input type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: | | |
| Old Serial Number | | | |
| New Serial Number | | | |
| Others Information | | | |
| Output Power: 110W | Limator Exciter A: Exciter B: | | |
| MER: | Attenuator Exciter A: Exciter B: | | |
| Remarks: | | | |
| Additional Information | | | |
| Temperature | Exterior (°C) | | |
| | Interior local (°C) | | |
| Mains fluctuations | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| Air cleanness | Yes | Dust inside the building | No |
| Transmitters on air/Total transmitters | | | |