



## Intervention Report

Date of Report: 15/11/2017		Date of Intervention : 15/11/2017	
Engineer's name: François-Joseph + Robin Pasquier			
<b>Station</b>			
Name: Tel Aviv (Tahanat Kemach)		MUX (CH ) : MUX1 C26	
Type of Transmitter:E100		Output Power: 475W	
<b>Failure information</b>			
Description:	Exciter B no GPS.		
Solution:	We made a hard reset of the exciter on site, now everything is working fine.		
Material Exchange?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    If Yes, Type:		
Old Serial Number			
New Serial Number			
<b>Others Information</b>			
Output Power: 475W	<b>Limiter</b> Exciter A: 17dB Exciter B: 17dB		
MER:	<b>Attenuator</b> Exciter A: 2.36dB Exciter B: 2.03dB		
Remarks: Shoulder : Exc A: 34dB Exc B: 34dB	VSWR : Exc A: 1.02 Exc B: 1.02		
<b>Additional Information</b>			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input type="checkbox"/> No		
Air cleanness		Dust inside the building	
Transmitters on air/Total transmitters			