



## Intervention Report

Date of Report: 24/12/17		Date of Intervention: 03/01/18		
Engineer's name: François-Joseph ROBERT				
<b>Station</b>				
Name: Radar		MUX 1 (CH 29)		
Type of Transmitter: Step0 E1000		Output Power: 5000W		
<b>Failure information</b>				
Description:		Amplifier #1 maintenance alarm.		
Solution:		I made a reset of the amplifier and put it back again. Amplifier is working good now.		
<b>Material Exchange?</b>		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type:		
Old Serial Number				
New Serial Number				
<b>Others Information</b>				
Power: 5000W		Limitor:		
MER:		Attenuator:		
Remarks:				
<b>Additional Information</b>				
Temperature		Exterior (°C)		n/a
		Interior local (°C)		n/a
Mains fluctuations		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness		Good	Dust inside the building	No
Transmitters on air/Total transmitters				