



Intervention Report

Date of Report: 05/01/17		Date of Intervention: 05/01/18	
Engineer's name: François-Joseph ROBERT			
Station			
Name: Hedera		MUX 1 (CH 29)	
Type of Transmitter: Gap Filler		Output Power: 110W	
Failure information			
Description:		No transition	
Solution:		I did a hard reset on the Gap Filler, it was working good after that.	
Material Exchange?		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type:	
Old Serial Number			
New Serial Number			
Others Information			
Power: 110W		<u>Limitor:</u>	
MER:		<u>Attenuator:</u>	
<u>Remarks:</u>			
Additional Information			
Temperature	Exterior (°C)	n/a	
	Interior local (°C)	n/a	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			