



Intervention Report

| | | | |
|----------------------------------------------|--------------------------------------------------------------------------------------|-----------------------------------|----|
| Date of Report: 07/01/2018 | | Date of Intervention : 07/01/2018 | |
| Engineer's name: Robin Pasquier | | | |
| Station | | | |
| Name: Har Mirbatz | | MUX (CH) : MUX3 C28 | |
| Type of Transmitter:E1000 | | Output Power: 4800W | |
| Failure information | | | |
| Description: | Presence alarm on amplifier 1 and alarm on cooling system | | |
| Solution: | Amplifier took out and put back, filter 2 changed and liquid adjusted | | |
| Material Exchange? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type: | | |
| Old Serial Number | | | |
| New Serial Number | | | |
| Others Information | | | |
| Output Power: 4800W | Limiter Exciter A: 9dB Exciter B: 8dB | | |
| MER: | Attenuator Exciter A:1.5dB Exciter B:1.6dB | | |
| Remarks: Shoulder : Exc A:39dB Exc B:40dB | | VSWR : Exc A:1.13 Exc B:1.12 | |
| Additional Information | | | |
| Temperature | Exterior (°C) | 19 | |
| | Interior local (°C) | 40 | |
| Mains fluctuations | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| Air cleanness | Good | Dust inside the building | No |
| Transmitters on air/Total transmitters | | | |