



Intervention Report

Date of Report: 08/01/2018		Date of Intervention : 08/01/2018	
Engineer's name: François-Joseph + Robin Pasquier			
Station			
Name: Rehovot		MUX (CH) : MUX1 C26	
Type of Transmitter: Gap Filler		Output Power: 110W	
Failure information			
Description:	Gapfiller was not responding, it was off. Certainly due to a power supply failure.		
Solution:	Gapfiller changed with the MUX2		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Gap Filler		
Old Serial Number	980579/0053		
New Serial Number	980606/0098		
Others Information			
Output Power: 110W		Limiter	
MER:		Attenuator	
Remarks: Shoulder :			
Additional Information			
Temperature	Exterior (°C)	/	
	Interior local (°C)	Good	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			