



## Intervention Report

Date of Report: 06/04/2018		Date of Intervention : 08/04/2018	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Hod Hasharon		MUX (CH ) : MUX1 C29	
Type of Transmitter: Gap Filler		Output Power: 110W	
<b>Failure information</b>			
Description:	Fan alarm		
Solution:	Fan changed on site		
<b>Material Exchange?</b>	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    If Yes, Type:		
Old Serial Number			
New Serial Number			
<b>Others Information</b>			
Output Power: 110W		Limiter	
MER:		Attenuator	
Remarks:			
<b>Additional Information</b>			
Temperature	Exterior (°C)	25	
	Interior local (°C)	25	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			