



Intervention Report

Date of Report: 09/02/2018		Date of Intervention : 11/02/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Eitanim		MUX (CH) : MUX3 C28	
Type of Transmitter:E1000		Output Power: 6900W	
Failure information			
Description:	Leak on a fan pipe		
Solution:	Pipe tightened		
Material Exchange?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type:		
Old Serial Number			
New Serial Number			
Others Information			
Output Power: 6900W	Limiter Exciter A: Exciter B:		
MER:	Attenuator Exciter A: Exciter B:		
Remarks: Shoulder : Exc A: Exc B:	VSWR : Exc A: Exc B:		
Additional Information			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			