



## Intervention Report

Date of Report: 14/11/17		Date of Intervention : 14/11/17	
Engineer's name: François-Joseph + Robin Pasquier			
<b>Station</b>			
Name: Tel El Ful		MUX (CH) : MUX1 C26	
Type of Transmitter:E100		Output Power: 1050W	
<b>Failure information</b>			
Description:	Output Power only at 80%		
Solution:	Amplifier changed		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Amplifier E100 (internal)		
Old Serial Number	5602564/015		
New Serial Number	5602543/014		
<b>Others Information</b>			
Output Power: 1050W		<b>Limiter</b>	
		Exciter A: 14dB Exciter B: 12dB	
MER:		<b>Attenuator</b>	
		Exciter A: 1.79dB Exciter B: 2.13dB	
Remarks: Shoulder : Exc A: 34dB Exc B: 35dB		VSWR : Exc A: 1.14 Exc B: 1.15	
<b>Additional Information</b>			
Temperature	Exterior (°C)	27	
	Interior local (°C)	24	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			