



## Intervention Report

Date of Report: 16/12/2017		Date of Intervention : 18/12/2017	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Bar Yehuda		MUX (CH ) : MUX1 C26	
Type of Transmitter:E100		Output Power: 700W	
<b>Failure information</b>			
Description:	Output Power at 88%, but 700W measured		
Solution:	Settings changed. Settings of attenuation and limitation stated for a output power of 100%		
Material Exchange?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    If Yes, Type:		
Old Serial Number			
New Serial Number			
<b>Others Information</b>			
Output Power: 700W	<b>Limiter</b> Exciter A: 19dB Exciter B: 19dB		
MER:	<b>Attenuator</b> Exciter A:2.52dB Exciter B:2.1dB		
Remarks: Shoulder : Exc A:39dB Exc B:40dB		VSWR : Exc A:1.18 Exc B:1.2	
<b>Additional Information</b>			
Temperature	Exterior (°C)	22	
	Interior local (°C)	20.4	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			