



## Intervention Report

Date of Report: 24/04/2018		Date of Intervention : 24/04/2018	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Har Mirbatz		MUX (CH) : MUX1 C26	
Type of Transmitter:E1000		Output Power: 5000W	
<b>Failure information</b>			
Description:	Breaker of amplifier 4 tripped		
Solution:	This problems occurred for the second time , amplifier changed by another		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Amplifier E1000		
Old Serial Number	5602324028		
New Serial Number	5602324017		
<b>Others Information</b>			
Output Power: 5000W		<b>Limiter</b>	
		Exciter A: 11dB Exciter B: 10dB	
MER:		<b>Attenuator</b>	
		Exciter A:1.68dB Exciter B:2.76dB	
Remarks: Shoulders : Exc A:34dB Exc B:33dB		VSWR : Exc A:1.03 Exc B:1.03	
<b>Additional Information</b>			
Temperature	Exterior (°C)	27	
	Interior local (°C)	25	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			