



## Intervention Report

Date of Report: 27/03/2018		Date of Intervention : 28/03/2018	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Tel Aviv (Mikve)		MUX (CH ) : MUX1 C26	
Type of Transmitter:E100		Output Power: 1400W	
<b>Failure information</b>			
Description:	GPS fault on Exciter A and no GPS signal on Exciter B		
Solution:	On Exciter A : The fault occurs rarely On Exciter B : Reset made and antenna switched with one of the MUX2 because more sensitive		
<b>Material Exchange?</b>	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    If Yes, Type:		
Old Serial Number			
New Serial Number			
<b>Others Information</b>			
Output Power: 1400W	<b>Limiter</b> Exciter A: Exciter B:		
MER:	<b>Attenuator</b> Exciter A: Exciter B:		
Remarks:			
<b>Additional Information</b>			
Temperature	Exterior (°C)	24	
	Interior local (°C)	24	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			