



Intervention Report

Date of Report: 12/03/2018		Date of Intervention : 12/03/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Givat Yoav (Bnei Yehouda)		MUX (CH) : MUX1 C29	
Type of Transmitter:E1000		Output Power: 1500W	
Failure information			
Description:	Synthetizer Alarm on the Exciter A, rf out fault on Exciter B		
Solution:	Hard reset made on Exciter A, Exciter B replaced		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Exciter (Sirius)		
Old Serial Number	57050110011		
New Serial Number	57049070042		
Others Information			
Output Power: 1500W	Limiter Exciter A: 14dB Exciter B: 3.21dB		
MER:	Attenuator Exciter A:1.67dB Exciter B:14dB		
Remarks: Shoulder : Exc A:41dB Exc B:41dB		VSWR : Exc A:1.12 Exc B:1.12	
Additional Information			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			