



Intervention Report

Date of Report: 25/04/2018		Date of Intervention : 25/04/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Givataim		MUX (CH) : MUX1 C26	
Type of Transmitter:E1000		Output Power: 3000W	
Failure information			
Description:	No output from the both exciters, after an electricity cut		
Solution:	Hard reset of the both exciters		
Material Exchange?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type:		
Old Serial Number			
New Serial Number			
Others Information			
Output Power: 3000W	Limiter Exciter A: 13dB Exciter B: 12dB		
MER:	Attenuator Exciter A:3.04dB Exciter B:3.74dB		
Remarks: Shoulders : Exc A:38dB Exc B:38dB		VSWR : Exc A:1.01 Exc B:1.01	
Additional Information			
Temperature	Exterior (°C)	24	
	Interior local (°C)	23	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			