



Intervention Report

Date of Report: 25/03/2018		Date of Intervention : 26/03/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Carmiel		MUX (CH) : All	
Type of Transmitter:		Output Power:	
Failure information			
Description:	No communication to the whole site, all MUXs		
Solution:	Switch changed		
Material Exchange?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type:		
Old Serial Number			
New Serial Number			
Others Information			
Output Power:	<div style="text-align: right;">Limiter</div> Exciter A: Exciter B:		
MER:	<div style="text-align: right;">Attenuator</div> Exciter A: Exciter B:		
Remarks: Shoulders : Exc A: Exc B:		VSWR : Exc A: Exc B:	
Additional Information			
Temperature	Exterior (°C)	24	
	Interior local (°C)	30	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			