



Intervention Report

| | | | |
|---|--|-----------------------------------|--------------------------------------|
| Date of Report: 26/01/2018 | | Date of Intervention : 28/01/2018 | |
| Engineer's name: François-Joseph + Robin Pasquier | | | |
| Station | | | |
| Name: Eitanim | | MUX (CH) : MUX3 C28 | |
| Type of Transmitter:E1000 | | Output Power: 6900W | |
| Failure information | | | |
| Description: | Power at 70%, 2 amplifiers showed as missing. | | |
| Solution: | Amplifier 2 and 6 took off and put back. | | |
| Material Exchange? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If Yes, Type: | | |
| Old Serial Number | | | |
| New Serial Number | | | |
| Others Information | | | |
| Output Power: | | | Limiter |
| | | | Exciter A: 5dB Exciter B: 4dB |
| MER: | | | Attenuator |
| | | | Exciter A:1.78dB Exciter B:1.99dB |
| Remarks: Shoulder : Exc A:35dB Exc B:36dB | | VSWR : Exc A:1.17 Exc B:1.17 | |
| Additional Information | | | |
| Temperature | Exterior (°C) | 16 | |
| | Interior local (°C) | 18 | |
| Mains fluctuations | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | |
| Air cleanness | Good | Dust inside the building | No |
| Transmitters on air/Total transmitters | | | |