



## Intervention Report

Date of Report: 30/12/2017		Date of Intervention : 30/12/2017	
Engineer's name: François-Joseph			
<b>Station</b>			
Name: Rosh HaAyin		MUX (CH) : MUX3 C32	
Type of Transmitter: Gap Filler		Output Power: 110W	
<b>Failure information</b>			
Description:	No output power.		
Solution:	I replaced the Gap Filler		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Gap Filler		
Old Serial Number	980117/0039		
New Serial Number	980579/058		
<b>Others Information</b>			
Output Power: 110W	<b>Limiter</b> Exciter A: Exciter B:		
MER:	<b>Attenuator</b> Exciter A: Exciter B:		
Remarks: Shoulder : Exc A: Exc B:		VSWR : Exc A: Exc B:	
<b>Additional Information</b>			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			