

Rack Firmware Summary

Export Device Firmware Information: [XML](#) [CSV](#)

Enclosure: C7000_DR

Primary Connection

Onboard Administrator Firmware Information

Bay	Model	Manufacturer	Serial Number	Part Number	Spare Part Number	Firmware Version
1	BladeSystem c7000 Onboard Administrator	HP	O98CMP0580	412142-B21	414055-001	4.50 Jul 24 2015

Enclosure Component Firmware Information

Bay	Device Model	Current Firmware Version	Available Firmware Version
-	BladeSystem c7000 Onboard Administrator Tray	1.7	1.7
-	BladeSystem c7000 Insight Display	2.2.2	2.2.2
1	Active Cool 200 Fan	2.9.4	2.9.4
2	Active Cool 200 Fan	2.9.4	2.9.4
3	Active Cool 200 Fan	2.9.4	2.9.4
4	Active Cool 200 Fan	2.9.4	2.9.4
5	Active Cool 200 Fan	2.9.4	2.9.4
6	Active Cool 200 Fan	2.9.4	2.9.4
7	Active Cool 200 Fan	2.9.4	2.9.4
8	Active Cool 200 Fan	2.9.4	2.9.4
9	Active Cool 200 Fan	2.9.4	2.9.4
10	Active Cool 200 Fan	2.9.4	2.9.4

Device Firmware Information

Bay	Device Model	Firmware Component	Current Version	Firmware ISO Version
1	ProLiant BL460c G1 Discovered: No	System ROM	115 05/02/2011	
		iLO2	2.29 Jul 16 2015	
		Power Management Controller	3.4	
2	ProLiant BL460c G7 Discovered: No	System ROM	127 08/16/2015	
		iLO3	1.87 Oct 27 2015	
		Power Management Controller	1.6	
3	ProLiant BL460c G7 Discovered: No	System ROM	127 08/16/2015	
		iLO3	1.87 Oct 27 2015	
		Power Management Controller	1.6	
6	ProLiant BL460c G6 Discovered: No	System ROM	124 05/20/2010	
		iLO2	2.05 Dec 16 2010	
		Power Management Controller	3.4	
9	ProLiant BL460c G7 Discovered: No	System ROM	127 08/16/2015	
		iLO3	1.87 Oct 27 2015	
		Power Management Controller	1.6	
10	ProLiant BL460c G7 Discovered: No	System ROM	127 08/16/2015	
		iLO3	1.87 Oct 27 2015	
		Power Management Controller	1.6	
14	ProLiant BL460c G6 Discovered: No	System ROM	124 08/16/2015	
		iLO2	2.29 Jul 16 2015	
		Power Management Controller	3.4	

Interconnect Firmware Information

Bay	Device Model	Firmware Version
1	HP 1/10Gb VC-Enet Module	3.62
2	HP 1/10Gb VC-Enet Module	3.62

*The Power Management Controller version is only available from ProLiant iLO 2 version 1.77 and later. Power Management Controller

firmware version 0.5 does not require an upgrade. The server blade must be power-cycled after upgrading the Power Management Controller version.