



## Intervention Report

Date of Report: 19/12/2017		Date of Intervention : 19/12/2017	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Givat Yoav (Bnei Yehouda)		MUX (CH) : MUX1 C29	
Type of Transmitter:E1000		Output Power: 1500W	
<b>Failure information</b>			
Description:	On Exciter A the output power was at 23%, Exciter B didn't works		
Solution:	Reset done on exciter A, exciter B changed		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Exciter (Sirius)		
Old Serial Number	5705011 0015		
New Serial Number	5705011 0011		
<b>Others Information</b>			
Output Power: 1500W		<b>Limiter</b>	
		Exciter A: 14dB Exciter B: 15dB	
MER:		<b>Attenuator</b>	
		Exciter A:1.67dB Exciter B:1.97dB	
Remarks: Shoulder : Exc A:41dB Exc B:39dB		VSWR : Exc A:1.12 Exc B:1.12	
<b>Additional Information</b>			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			