



## Intervention Report

Date of Report: 09/04/2018		Date of Intervention : 10/04/2018	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Givat Yoav (Bnei Yehouda)		MUX (CH ) : MUX3 C32	
Type of Transmitter:E100		Output Power: 900W	
<b>Failure information</b>			
Description:	Output power at 60%		
Solution:	One power supply of an amplifier and one amplifier changed		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Amplifier E100 (internal)		
Old Serial Number	5602580058		
New Serial Number	56A8000001		
<b>Others Information</b>			
Output Power: 900W	<b>Limiter</b> Exciter A: 7dB Exciter B: 7dB		
MER:	<b>Attenuator</b> Exciter A:1.84dB Exciter B:1.8dB		
Remarks: Shoulders : Exc A:36dB Exc B:36dB		VSWR : Exc A:1.15 Exc B:1.18	
<b>Additional Information</b>			
Temperature	Exterior (°C)	22	
	Interior local (°C)	22	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			