



## Intervention Report

Date of Report: 14/11/17		Date of Intervention : 14/11/17	
Engineer's name: François-Joseph + Robin Pasquier			
<b>Station</b>			
Name: Eshel Be'er Sheva		MUX (CH) : MUX1 C26	
Type of Transmitter:E100		Output Power: 1500W	
<b>Failure information</b>			
Description:	Output power at 67%		
Solution:	Amplifier changed		
<b>Material Exchange?</b>	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Amplifier E100 (internal)		
Old Serial Number	5602380/064		
New Serial Number	5602565/010		
<b>Others Information</b>			
Output Power: 1500W		<b>Limiter</b>	
		Exciter A: 14dB Exciter B: 13dB	
MER:		<b>Attenuator</b>	
		Exciter A: 2.44dB Exciter B: 1.83dB	
Remarks: Shoulder : Exc A: 36dB Exc B: 38dB		VSWR : Exc A: 1.21 Exc B: 1.26	
<b>Additional Information</b>			
Temperature	Exterior (°C)	28	
	Interior local (°C)	26	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			