



## Intervention Report

Date of Report: 20/03/2018		Date of Intervention : 21/03/2018	
Engineer's name: Robin Pasquier			
<b>Station</b>			
Name: Kiryat Gat		MUX (CH ) : MUX1 C26	
Type of Transmitter: Gap Filler		Output Power: 110W	
<b>Failure information</b>			
Description:	Gap Filler switches off every few seconds		
Solution:	Gap Filler changed		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No    If Yes, Type: Gap Filler		
Old Serial Number	9801170040		
New Serial Number	9806060076		
<b>Others Information</b>			
Output Power: 110W		Limiter	
MER:		Attenuator	
Remarks:			
<b>Additional Information</b>			
Temperature	Exterior (°C)	23	
	Interior local (°C)	27	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			