



Intervention Report

Date of Report: 29/01/2018		Date of Intervention : 29/01/2018	
Engineer's name: François-Joseph + Robin Pasquier			
Station			
Name: Tel Aviv (Ramat Elyho)		MUX (CH) : MUX1 C26	
Type of Transmitter:E100		Output Power: 1000W	
Failure information			
Description:	Output power 50%.		
Solution:	We changed the amplifier number #3 by a new one.		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Amplifier E100 (internal)		
Old Serial Number	5602540/021		
New Serial Number	5602331/028		
Others Information			
Output Power: 1000W		Limiter	
		Exciter A: 19dB Exciter B: 19dB	
MER:		Attenuator	
		Exciter A:2.3dB Exciter B:1.87dB	
Remarks: Shoulder : Exc A:39dB Exc B:38dB		VSWR : Exc A:1.22 Exc B:1.23	
Additional Information			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input type="checkbox"/> No		
Air cleanness		Dust inside the building	
Transmitters on air/Total transmitters			