



Intervention Report

Date of Report: 30/04/2018		Date of Intervention : 30/04/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Ramat Aviv		MUX (CH) : MUX3 C28	
Type of Transmitter:E100		Output Power: 300W	
Failure information			
Description:	Shoulders very low, impossible to adjust it, intermittent problem of the TS inputs		
Solution:	Exciter changed		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type:		
Old Serial Number	5705105004		
New Serial Number	5602324017		
Others Information			
Output Power: 300W		Limiter	
		Exciter A: 18dB	
MER:		Attenuator	
		Exciter A:4.51dB	
Remarks: Shoulders : Exc A:42dB		VSWR : Exc A:1.2	
Additional Information			
Temperature	Exterior (°C)	29	
	Interior local (°C)	22	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			