

Rack Firmware Summary

Export Device Firmware Information: [XML](#) [CSV](#)

Enclosure: CZ25370F5X

Primary Connection

Onboard Administrator Firmware Information

Bay	Model	Manufacturer	Serial Number	Part Number	Spare Part Number	Firmware Version
1	BladeSystem c7000 DDR2 Onboard Administrator with KVM	HP	OB52CP0412	456204-B21	708046-001	4.60 Jun 17 2016
2	BladeSystem c7000 DDR2 Onboard Administrator with KVM	HP	OB57CP4841	456204-B21	708046-001	4.60 Jun 17 2016

Enclosure Component Firmware Information

Bay	Device Model	Current Firmware Version	Available Firmware Version
-	BladeSystem c7000 Onboard Administrator Tray	1.7	1.7
-	BladeSystem c7000 Insight Display	2.8.3	2.8.3
1	Active Cool 200 Fan	2.7.4	2.7.4
2	Active Cool 200 Fan	2.9.4	2.9.4
3	Active Cool 200 Fan	2.7.4	2.7.4
4	Active Cool 200 Fan	2.7.4	2.7.4
5	Active Cool 200 Fan	2.7.4	2.7.4
6	Active Cool 200 Fan	2.9.4	2.9.4
7	Active Cool 200 Fan	2.7.4	2.7.4
8	Active Cool 200 Fan	2.9.4	2.9.4
9	Active Cool 200 Fan	2.7.4	2.7.4
10	Active Cool 200 Fan	2.7.4	2.7.4
-	HP Location Discovery Services	2.1.3	2.1.3

Device Firmware Information

Bay	Device Model	Firmware Component	Current Version	Firmware ISO Version
1	ProLiant BL460c Gen9 Discovered: No	System ROM	I36 09/12/2016	
		iLO4	2.50 Sep 23 2016	
		Power Management Controller	1.0.9	
2	ProLiant BL460c Gen9 Discovered: No	System ROM	I36 09/12/2016	
		iLO4	2.50 Sep 23 2016	
		Power Management Controller	1.0.9	
3	ProLiant BL460c G7 Discovered: No	System ROM	I27 08/16/2015	
		iLO3	1.88 Jul 13 2016	
		Power Management Controller	1.6	
4	ProLiant BL460c G7 Discovered: No	System ROM	I27 08/16/2015	
		iLO3	1.88 Jul 13 2016	
		Power Management Controller	1.6	
9	ProLiant BL460c Gen9 Discovered: No	System ROM	I36 09/12/2016	
		iLO4	2.50 Sep 23 2016	
		Power Management Controller	1.0.9	
10	ProLiant BL460c Gen9 Discovered: No	System ROM	I36 09/12/2016	
		iLO4	2.50 Sep 23 2016	
		Power Management Controller	1.0.9	
11	ProLiant BL460c G7 Discovered: No	System ROM	I27 08/16/2015	
		iLO3	1.88 Jul 13 2016	
		Power Management Controller	1.6	
12	ProLiant BL460c G7 Discovered: No	System ROM	I27 08/16/2015	
		iLO3	1.88 Jul 13 2016	
		Power Management Controller	1.6	

Interconnect Firmware Information

Bay	Device Model	Firmware Version
1	HP VC FlexFabric-20/40 F8 Module	4.50
2	HP VC FlexFabric-20/40 F8 Module	4.50

*The Power Management Controller version is only available from ProLiant iLO 2 version 1.77 and later. Power Management Controller firmware version 0.5 does not require an upgrade. The server blade must be power-cycled after upgrading the Power Management Controller version.