



## Intervention Report

Date of Report: 31/12/2017		Date of Intervention : 31/12/2017	
Engineer's name: François-Joseph			
<b>Station</b>			
Name: Netanya		MUX (CH ) : MUX3 C32	
Type of Transmitter:E100		Output Power: 1800W	
<b>Failure information</b>			
Description:	Output power 65%.		
Solution:	One amplifier had a power supply fault, I fixed the amplifier.		
<b>Material Exchange?</b>	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No    If Yes, Type:		
Old Serial Number			
New Serial Number			
<b>Others Information</b>			
Output Power: 1800W		Limiter	
MER:		Attenuator	
Remarks: Shoulder : Exc A:42dB Exc B:41dB			
<b>Additional Information</b>			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input type="checkbox"/> No		
Air cleanness	Dust inside the building		
Transmitters on air/Total transmitters			