



Intervention Report

Date of Report: 15/03/2018		Date of Intervention : 15/03/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Ashkelon		MUX (CH) : MUX1 C26	
Type of Transmitter:E100		Output Power: 300W	
Failure information			
Description:	No broadcasting, amplifier faulty		
Solution:	Amplifier changed		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Amplifier E100 (internal)		
Old Serial Number	5602623060		
New Serial Number	56pvnc1349		
Others Information			
Output Power: 300W	Limiter Exciter A: 17dB		
MER:	Attenuator Exciter A:2.22dB		
Remarks: Shoulder : Exc A:40dB		VSWR : Exc A:1.29	
Additional Information			
Temperature	Exterior (°C)	23	
	Interior local (°C)	25	
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	A bit
Transmitters on air/Total transmitters			