



Intervention Report

Date of Report: 28/01/2018		Date of Intervention : 28/01/2018	
Engineer's name: François-Joseph			
Station			
Name: Givataim		MUX (CH) : MUX1 C26	
Type of Transmitter:E1000		Output Power: 3000W	
Failure information			
Description:	Output power is only 65%, Amplifier 1 faulty		
Solution:	Amplifier changed		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Amplifier E1000		
Old Serial Number	5602324/017		
New Serial Number	5602441/009		
Others Information			
Output Power: 3000W		Limiter Exciter A: 13dB Exciter B: 12dB	
MER:		Attenuator Exciter A:3.04dB Exciter B:3.74dB	
Remarks: Shoulder : Exc A:37dB Exc B:37dB		VSWR : Exc A:1.01 Exc B:1.01	
Additional Information			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			