



Intervention Report

Date of Report: 03/04/2018		Date of Intervention : 03/04/2018	
Engineer's name: Robin Pasquier			
Station			
Name: Maale Edomim		MUX (CH) : MUX1 C26	
Type of Transmitter: Gap Filler		Output Power: 110W	
Failure information			
Description:	No Output Power		
Solution:	Gapfiller changed		
Material Exchange?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No If Yes, Type: Gap Filler		
Old Serial Number	980579059		
New Serial Number	9801170040		
Others Information			
Output Power: 110W		Limiter	
MER:		Attenuator	
Remarks:			
Additional Information			
Temperature	Exterior (°C)		
	Interior local (°C)		
Mains fluctuations	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Air cleanness	Good	Dust inside the building	No
Transmitters on air/Total transmitters			